APPENDIX G

College of the Desert West Valley Campus Photo Survey

Prepared by

Terra Nova Planning & Research, Inc. 42635 Melanie Place, Suite 101 Palm Desert, CA 92211

November 18, 2014

Terra Nova/Desert Community College District COD West Valley Campus Master Plan/Draft Environmental Impact Report Technical Appendices

COLLEGE OF THE DESERT

WEST VALLEY CAMPUS

PHOTO SURVEY (November 18, 2014)

- 1. & 2. Two views looking west to the existing Camelot Festival Theaters located in the southwest corner of the project planning area. Parking for the theater has been through a reciprocal parking agreement between the mall and theaters.
- 3. View looking northeast from the north parking lot to the existing Jack in the Box restaurant.
- 4. View looking south from the north parking lot to the north elevation of the existing mall. This was one of the main mall entrances and reflects the last remodeling effort.
- 5. View of one of the mall service and delivery areas showing a loading entrance, utility closets and service drive.
- 6. View of narrow loading area located between department store and supermarket spaces. Visibility into this space is obstructed by other improvements to west.
- 7. Partial view of the mall south elevation facing Baristo Road and the high school. Note partial patching of signage mountings and graffiti paint-overs.
- **8.** View northeast to northwest corner of mall building, which housed the Vons supermarket. In addition to evidence of graffiti over-painting, there is soffit damage in the arch element on this portion of the west façade.
- 9. View looking northwest toward the eastern portion of the south elevation. Includes a loading dock and mechanical/electrical equipment enclosure. Note lack of visual relief.
- 10. View of west entry into what was a major mall entrance that accessed the main department store and central mall court.
- 11. Southerly-most store entrance on the east façade of the mall (facing Farrell Drive). Was access to a department store.
- 12. Southeast corner of mall building showing entrance shown in Photo 11. Note graffiti paint-overs, and patched building repairs.























